

Donaldson Coal Abel Mine CCC Meeting

12th September 2022



Abel Update

- Abel mine continues on Care and Maintenance

Environmental Update


- No Community Complaints or Environmental Incidents since last meeting.
- The Environment Protection Licence (EPL) Annual Review has recently been submitted with 3 identified non conformances.
 1. Dust monitoring continuous recording disruption – power
 2. Water samples not collected due to dry sampling point
 3. Water discharge from pipe impacted by fire
- Rehabilitation Management Plan's for Abel and Donaldson were recently submitted to the Resources Regulator for review and approval. Final document can be found on the Doncoal website.

Environmental Monitoring Update


- Monitoring has remained consistent throughout the period with no additional monitoring taking place.
- An electrical fault was identified at the dust monitor located at Black Hill School that was causing intermittent faults during rainfall events.

Abel PM10 Monitoring

Black Hill School PM₁₀ E-Sampler



Abel Underground Coal Mine Rainfall – 2021/22



Property Update

- Inspections adjacent to Avalon Estate continue.
- Follow Up Hazard Reductions in the Bushland Conservation Area have been postponed due to wet conditions.
- Illegal access points continue to be blocked onsite.